

BEST COPY

AVAILABLE

*BEST - THRU-OUT
FOLDER*

Schedule III

Last No. 2 Revision 7

| Rev | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|-----|---------------|------------|---|---------------|---|------------------------|-----------------------|-------|--|------------|-------------|
| | | | | | | Depot Purchase Request | Factory Maint. Spares | Total | | | |
| G-1 | 234 | 732815-501 | "D" Panel Assy. - Cross | 73-B | | 0 | 1 | 1 | | 1,004.43 | 1,004.43 |
| G-2 | 235 | 730185-167 | Dowel Pin 1/8 dia. x 1 1/4 lg. /s Bl. Ox. | HS-732 | | 0 | 100 | 100 | | 24.33 | 24.33 |
| G-3 | 236 | 730187-115 | Retaining Ring - Stl. Bl. Ox. | HS-732 | Truarc #5555-12 | 0 | 200 | 200 | | 24.24 | 48.48 |
| G-4 | 237 | 738097 | Washer - Bevelled | HS-732 | | 0 | 87 | 87 | | 1.10 | 95.70 |
| G-5 | 238 | 738203 | Clutch - Disc | 73-B | | 0 | 36 | 36 | | 1.53 | 55.08 |
| G-6 | 239 | 732002-76 | Disc - Lug (Brake Disc) | 73-B | | 0 | 32 | 32 | | .57 | 18.24 |
| G-7 | 240 | 738079 | Nut - Latch Pivot, Bottom | HS-732 | | 0 | 150 | 150 | | 1.26 | 189.00 |
| G-8 | 241 | 732487-C | Bearing - Film Spool - 73-B Outboard | Film Spool | | 0 | 20 | 20 | | 9.48 | 189.60 |
| G-9 | 242 | 730155-96 | Button Plug for 11/32 hole /s Bl. Ox. | HS-732 | United Carr HS-5141 Approved For Release 1999/09/08 : CIA-RDP81B00879R000500090005-7 | 0 | 150 | 150 | | 32.69 | 49.04 |

Schedule B

List No. 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Serial Number | Quantity | | | | Unit Price | Total Price |
|------|---------------|------------|---|---------------|------------------------------------|------------------------|--------|--------------|-------|------------|-------------|
| | | | | | | Depot Purchase Request | Factor | Maint Spares | Price | | |
| G-1 | 243 | 730190-21 | Brush Assy., Motor | 73-B | 2-1257 | 0 | 24 | 24 | 1.59 | 38.16 | |
| G-11 | 244 | 730190-22 | Brush Assy., Motor | 73-B | 8080-1 | 0 | 24 | 24 | 3.09 | 74.16 | |
| G-12 | 245 | 730190-23 | Brush Assy., Motor | 73-B | 8205 | 0 | 24 | 24 | 3.75 | 90.00 | |
| G-13 | 246 | 730190-24 | Brush Assy., Motor | 73-B | 4013 | 0 | 24 | 24 | 2.12 | 50.88 | |
| G-14 | 247 | 730190-25 | Brush Assy., Motor | 73-B | 3443 | 0 | 24 | 24 | 1.06 | 25.44 | |
| G-15 | 248 | 738126-E | Cam - Switch | HS-732 | List 2 - Per 8 cents | 0 | 70 | 70 | 4.14 | 289.80 | |
| G-16 | 249 | 735452-126 | .0937 Dia. Reamer (high Speed Steel) | 73-B | | 0 | 3 | 3 | 4.45 | 13.35 | |
| G-17 | 250 | 735452-127 | .249 Dia. Reamer (High Speed Steel) | 73-B | | 0 | 3 | 3 | 5.74 | 17.22 | |
| G-18 | 74 | 730175-48 | See Screw 4-32 x 1/2 Hd. Cup pt. Nylon | | 1/4" length | 0 | 100 | 100 | 20.83 | 20.83 | |

Date 31 August 1957

Page 3 of 10

Schedule III

List No. 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|------|---------------|-----------|--|---------------|-----------------------------------|------------------------|-----------------------|---------------|------|------------|-------------|
| | | | | | | Depot Purchase Request | Factory Maint. Spares | Total | | | |
| G-16 | 251 | 730151-26 | Holder, Fuse-Min. for 1/4 x 1 1/4 Fuse | HS-732 | Littlefuse | 0 | 70 | 15225 (70) | .77 | 53.90 | |
| G-20 | 252 | 730151-31 | Fuse - 1 amp. Quick acting | HS-732 | Littlefuse | 0 | 175 | (175) | .20 | 35.00 | |
| G-21 | 253 | 738043-NC | Plate - Limit Switch | HS-732 | | 0 | 70 | (70) X 2.97 | 2.79 | 207.90 | |
| G-22 | 254 | 738006-C | Decal - Wiring Diagram | HS-732 | | 0 | 70 | (70) | 1.97 | 137.90 | |
| G-23 | 255 | 738113-NC | Plate - Switch Cam Adjusting | HS-732 | | 0 | 75 | (75) | 4.17 | 312.75 | |
| G-24 | 256 | 738142-C | Worm Gear - Modified | HS-732 | | 0 | 40 | (40) | 7.49 | 299.60 | |
| G-25 | 257 | 732956-NC | Spacer | 73-B | | 0 | 20 | (20) | 2.67 | 53.40 | |
| G-26 | 258 | 738337-A | Doubler - Oblique Drive | 73-B | | 0 | 20 | (20) | 3.32 | 66.40 | |
| G-27 | 259 | 738338-NC | Spacer | | | 0 | 10 | (10) | 3.88 | 38.80 | |

Date 31 August 1957

Page 4 of 10

List No. 2

Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|------|---------------|------------|-----------------------------|---------------|--|------------------------|---------------|--------|-------|------------|-------------|
| | | | | | | Depot Purchase Request | Factor Maint. | Spares | Total | | |
| G-29 | 260 | 737625-B | Bolt - Adjust Arm Assy. | 73-B | | 0 | 5 | 5 | 5 | 25.24 | 126.20 |
| G-29 | 261 | 730185-135 | Pin - Drive- Lok 3/32 x 1/4 | 73-B | Type A | 0 | 500 | 500 | 500 | 12.08 | 60.40 |
| G-30 | 262 | 730151-42 | Fuse Holder - 2 Pole | HS-732 | Littlefuse for 3AG fuse #357002 Type S | 0 | 70 | 70 | 70 | .60 | 42.00 |
| G-31 | 263 | 738141-2 | Spacer - Shim Drive | HS-732 | | 0 | 200 | 200 | 200 | 25.44 | 50.88 |
| G-32 | 264 | 738141-3 | Spacer - Shim Drive | HS-732 | | 0 | 200 | 200 | 200 | 25.44 | 50.88 |
| G-33 | 265 | 738141-5 | Spacer - Shim Drive | HS-732 | | 0 | 200 | 200 | 200 | 19.81 | 39.62 |
| G-34 | 266 | 738141-15 | Spacer - Shim Drive | HS-732 | | 0 | 200 | 200 | 200 | 1.63 | 32.60 |
| G-35 | 267 | 738141-60 | Spacer - Shim Drive | HS-732 | 15110 | 0 | 200 | 200 | 200 | 2.25 | 45.00 |
| G-36 | 268 | 735457-NC | Gage Assy. - Film Roller | 73-B | | 0 | 8 | 8 | 8 | 243.52 | 2,748.16 |

Schedule B

Last No. 2 Revision 7

| Rev. | Lane Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|------|---------------------|-------------|-------------------------------------|---------------------|--------------------------------------|------------------------------|-----------------------------|-------|--------|---------------|----------------|
| | | | | | | Depot Purchase Request | Factory Maint. Spares | Total | | | |
| G-37 | 43 | 732667-B | Motor Assy. | 73-B | | 0 | 4 | 4 | | 34.05 | 136.20 |
| G-38 | 108 | 732937-C | IMC & Metering Assy. | 73-B | | 0 | 4 | 4 | 152.58 | 459.04 | 1,836.16 |
| G-39 | 269 | 730187-123 | Ring, Retaining | HS-732 | Truarc #5000-50 | 0 | 100 | 100 | | 53.42/c | 53.42 |
| G-40 | 270 | 738124-25 C | Spacer - Trip Latch | HS-732 | | 0 | 100 | 100 | | 63.52/c | 63.52 |
| G-41 | 271 | 738362-7 | Bearing - Flanged | 73-B | ASCO #251-277-20-304 | 0 | 26 | 26 | | 1.32 | .32 |
| G-42 | 272 | 732447-D | Channel | 73-B | | 0 | 10 | 10 | | 34.13 | 341.30 |
| G-43 | 273 | 730185-66 | Dowel Pin 1/8 dia. x 1/2 lg. s/s | HS-732 | | 0 | 100 | 100 | | 29.33/c | 29.33 |
| G-44 | 274 | 738024-B | Bearing - Ring Support | HS-732 | | 0 | 200 | 200 | | 412.16/c | 824.32 |
| G-45 | 275 | 738028-F | Shaft - Idler Gear | HS-732 | | 0 | 20 | 20 | | 29.47 | 589.40 |

Serial 16

List No 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total |
|------|---------------|--------------|-----------------------------------|---------------|---|------------------------|--------|--------------|--------|------------|--------|
| | | | | | | Depot Purchase Request | Factor | Maint Spares | Total | | |
| G-47 | 70 | 730170-68 | Bearing, Ball .196 ID x .7480D | 73-B | ND #87035 | 0 | 10 | (10) | 152.15 | 3.45 | 34.50 |
| G-47 | 64 | 730145-3 | Diode | 73-B | Union Switch #S3W3PL | 0 | 27 | (27) | | 1.81 | 48.87 |
| G-48 | 276 | 730175-59 | Screw - Set | 73-B | #10-32 x 3/8 Lg. Hex. Soc. Flat pt. s/a b/o | 0 | 100 | (100) | | 26.10 | 26.10 |
| G-49 | 277 | 737692-A | Plate - Direction | 73-B | | 0 | 8 | (8) | | 6.72 | 53.76 |
| G-50 | 278 | 738080-E | Solenoid - Trip | HS-732 | | 0 | 10 | (10) | 152.58 | 25.08 | 250.80 |
| G-51 | 279 | 730129-39 | Switch (Start) Ship as #738002-23 | HS-732 | Electro - Snap | 0 | 15 | (15) | | 3.04 | 45.60 |
| G-52 | 149 | Item Deleted | | | | | | | | | |
| G-53 | 280 | 730129-38 | Switch (Limit) Ship as #738002-18 | HS-732 | | 0 | 70 | (70) | | 1.89 | 132.30 |

Work Authorization
Factor Maintenance Spares

Date 31 August 1957

Page 7 of 10

Schedule III

List No. 2 Revision 7

Approved For Release 1999/09/08 : CIA-RDP81B00879R000500090005-7

Approved For Release 1999/09/08 : CIA-RDP81B00879R000500090005-7

| Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|---------------|-----------|--|---------------|-----------------------------------|----------|--------|-------|--------|------------|-------------|
| | | | | | Request | Factor | Maint | Spares | | |
| G-089 | 730129-26 | Switch B-2 | HS-732 | Milliswitch | 0 | 46 | 46 | 1525 | 2.36 | 108.56 |
| G-103 | | Deleted | | | | | | 46 | | |
| G-099 | | Deleted | | | | | | | | |
| G-100 | 738010-2D | Blade Assembly #2 | HS-732 | <i>List 2 - Per 9 Cancel</i> | | 30 | 30 | 30 | 25.50 | 765.00 |
| G-101 | 738010-3D | Blade Assembly #3 | HS-732 | <i>List 2 - Per 9 Cancel</i> | | 30 | 30 | 30 | 25.50 | 765.00 |
| G-102 | 738010-4D | Blade Assembly #4 | HS-732 | <i>List 2 - Per 9 Cancel</i> | | 30 | 30 | 30 | 25.50 | 765.00 |
| G-281 | 730175-58 | Screw, 6-32 x 1/4" Slot Hd. Flat point Nylon | 73-B | (Replaces 730175-48) | 0 | 70 | 70 | 70 | .30 | 21.00 |
| G-271 | 738362-7 | Bearing .251 I.D. x .377 O.D. | 73-B | Asco 251-377-20-304 | 0 | 12 | 12 | 12 | 1.36 | 16.32 |
| G-110 | 732602-2 | Micropositioner Type L | B-Prog. | Barber - Coleman AYLZ -3639S | 0 | 8 | 8 | 8 | 33.19 | 265.52 |

Schedule III

List No. 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | Unit Price | Total Price |
|------|---------------------|-----------|-------------------------------|---------------------|--------------------------------------|------------------------------|-----------------------------|--------|---------------|----------------|
| | | | | | | Depot Purchase Request | Factory Maint. Spares | Total | | |
| G-65 | 131 | 738021-C | Spacer - Bearing Shaft | HS-732 | | 0 | 60 | 152-60 | 3.71 | 222.60 |
| G-64 | 033 | 730145-4 | Rectifier - Center Mount | 73-B | G. E. IN152 | 0 | 50 | 50 | 3.13 | 156.50 |
| G-65 | 184 | 738380 NC | Contact Assembly | 73-B | | 0 | 60 | 60 | 9.01 | 540.60 |
| G-66 | 029 | 730125-13 | Relay-Time Delay | 73-B | G. V. Controls HF-04 N-28VDC | 0 | 10 | 10 | 26.52 | 265.20 |
| G-67 | 164 | 738362-9 | Lamp 2.3 volt 2-56 thd. | 73-B | Type-CM110-E | 0 | 36 | 36 | 2.05 | 73.80 |
| G-68 | 155 | 730160-66 | Wire - 24 Ga. Black | 73-B | BU19 x 36 CA-5-5611 | 0 | 150 | 150 | 5.40 | 8.10 |
| G-69 | 187 | 738362-8 | Bearing .189 I.D. x .315 O.D. | 73-B | Asco 189-315-16-284 | 0 | 6 | 6 | 1.97 | 11.82 |
| G-70 | 064 | 730145-3 | Diode S3W3PL | 73-B | Union Switch | 0 | 100 | 100 | 180.49 | 180.49 |

Date 31 August 1957

Factory Maintenance Spares

Page 9 of 10

Schedule III

List No. 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used Or | Mfg. Catalog Type or Spec. Number | Quantity | | | Unit Price | Total Price |
|------|---------------------|--------------|-------------------------|---------------------|--------------------------------------|------------------------------|-----------------------------|-------|---------------|----------------|
| | | | | | | Depot Purchase Request | Factory Maint. Spares | Total | | |
| G-71 | 032 | 732602-32 | Relay | Prog. | Advance Pc3C-24VDC | 0 | 10 | 10 | 12.21 | 122.10 |
| G-72 | 042 | 732602-5 | Relay | Prog. | Advance PG2A-24VDC | 0 | 10 | 10 | 13.04 | 130.40 |
| G-73 | 282 | Item Deleted | | | | | | | | |
| G-74 | 283 | Item Deleted | | | | | | | | |
| G-75 | 284 | Item Deleted | | | | | | | | |
| G-76 | 165 | 738148 "A" | Spring -Arresting Latch | HS-732 | | 0 | 12 | 12 | 3.45 | 41.40 |
| G-77 | 285 | 738088-16A | Plate-Aperture F/16 | HS-732 | | 0 | 36 | 36 | 5.98 | 215.28 |
| G-78 | 286 | 738088-22A | Plate - Aperture F/22 | HS-732 | | 0 | 36 | 36 | 5.98 | 215.28 |

Date 31 August 1957

Page 10 of 10

Schedule III

List No. 2 Revision 7

| Rev. | Line Item No. | Part No. | Description | Model Used On | Mfg. Catalog Type or Spec. Number | Quantity | | | | Unit Price | Total Price |
|-------------|---------------|------------|--|-----------------|-----------------------------------|------------------------|--------------|--------|-------|------------|-------------|
| | | | | | | Depot Purchase Request | Factor Maint | Spares | Total | | |
| G-79 | 105 | 738143-B | Motor and Gear Assembly | HS-732 | | 0 | 8 | 8 | 1522 | 164.16 | 1,313.28 |
| G-80 | 288 | 732961 | Bracket - Relay | 73-B | | 0 | 27 | 27 | | 6.24 | 168.48 |
| G-81 | 31 | 730125-9 | Relay - Sub Miniature DPDT 24-28 VDC | 73-B | Allied Controls MHO-6D | 0 | 27 | 27 | | 22.91 | 618.57 |
| G-82 | 289 | 732958-NC | Cam Assy. - I. M. C. | Film Drive 73-B | 23-15258 3-15270 1-15323 | 0 | 27 | 27 | | 112.60 | 3,040.20 |
| G-83 | 287 | 730184-107 | Spacer - Shim 303 S/S 1/8 ID x 3/16 OD x .012 thick | 73-B | PIC #B4-5 | 0 | 300 | 300 | | 25.22 | 75.66 |
| Grand Total | | | | | | | | | | | 21,301.19 |